

MicroConverter[®], Multi-Channel 12-bit ADC with Embedded FLASH MCU

Errata Sheet ADuC812

A. This Errata sheet represents the known bugs, anomalies and work-arounds for the ADuC812 MicroConverter.

B. The Errata listed, apply to all ADuC812 packaged material branded as follows:

(Production Material)

ADUC812BS

Date Stamp AD Logo C

Lot Number

(Note: The indentifier 'C' after the ADLogo on the second line of the brand)

C. Errata Sheets referring to previous silicon revisions are available on our web-site at http://www.analog.com/microconverter/erratasheets.html

D. Because of silicon revisions and improved work-arounds, this Errata Sheet will be updated periodically. Please find the latest Errata Sheet listed on the World Wide Web at:

http://www.analog.com/microconverter/erratasheets.html

E. Analog Devices Inc. is committed, through future silicon revisions to continuously improve silicon functionality. Analog Devices Inc. will use its best endeavors to ensure that these future silicon revisions remain compatible with your present software/systems that implement the recommended work-arounds outlined in this document.

ADuC812 Errata Sheet

812_S01. ADC FUNCTION - ADC CONVERSION IN DMA MODE:

Background: The ADC can be triggered by 1 of 4 trigger events in Normal and DMA

operating modes, namely: Single Software Conversion, Continuous Software Conversions, External Pin Triggered Conversions and Timer2 triggered Conversions. DMA mode is initiated by setting the DMA bit in the ADCCON2 SFR and the DMA controller proceeds starting from the external data memory address indicated by the DMA address SFRs DMAL/H/P. Once a DMA conversion sequence is complete, both the DMA bit and the bit controlling the conversion mode are reset by the

DMA controller.

Issue A: DMA operation will not execute when triggered from Timer2 driven

conversions unless when configuring the ADC, ADCCON2 is written

prior to ADCCON1.

Work-Around A: For Timer2 triggered DMA conversions, ensure that the correct

configuration sequence is used for the ADC, i.e. configure ADCCON2

then ADCCON1.

Issue B: DMA operation will not execute when triggered from Timer2 driven

conversions unless DMA Address (DMAL/H/P) is initially set to

000000H.

Work-Around B: For Timer2 triggered DMA conversions, ensure that the DMA start

address is set to 000000H.

Related Issues: None.

812_S02. UART FUNCTION - MULTIPROCESSOR COMMUNICATIONS MODE:

Background: UART Modes 2 and 3 (programmed via SCON) have a special provision

for multiprocessor communications. In these modes, nine data bits are received and the ninth bit goes into RB8. In this mode the port can be programmed so that when the stop bit is received, the serial port interrupt is activated only if RB8(SCON) = 1. This feature is enabled by setting the

SM2 bit in SCON.

Issue: With SM2 set, the serial port interrupt is set each time a stop bit is

received, regardless of the state of the RB8 bit.

Work-Around: Implement a software polling scheme in the Serial Port ISR so that the

state of the RB8 bit is checked on entering the ISR. If RB8 is '0' then a 'RETI' is executed to exit the ISR immediately, and only if RB8 is set will

the ISR function be executed.

Related Issues: None.

ADuC812 Errata Sheet

812_S03. UART FUNCTIONALITY - BAUD RATE GENERATION IN SPLIT TIMER MODE:

Background: Timer 0 can be enabled as two 8-bit timers (Mode 3). Since the overflow

flag for timer 1 is used by timer 0 in split timer mode, timer 1 can only be used as either a baud rate generator or as a timer as long as it does not

require interrupts.

Issue: When the timers are configured as above with timer 1 as a baud rate

generator the reload value in TH1 fails to be loaded into TH0, generating

the incorrect baud rate.

Work-Around: Pending

Related Issues: All other Timer and Baud Rate generation modes operate correctly.

812 S04. PORT 2 INTERNAL ACTIVE PULL-UP FUNCTIONALITY:

Background: As with standard 8051 compatible Port functionality, Port 2 (P2.0 - P2.7)

feature weak internal pull-up resistors and will source current (Logic 0 input current, datasheet) when pulled low externally. On a 0-to-1 transition, an additional pullup is turned on for 2 master clock periods to

help increase transition speed.

Issue: On Port 2 pins, the additional pullup resistor does not come on during the

required 2 clock periods when these pins are being driven as digital

outputs.

Work-Around: Pending

Related Issues: Port 2 pins operate correctly when operating as part of the external

memory interface on the device.

812_S05. FLASH/EE MEMORY - 3V PROGRAMMING:

Background: The ADuC812 contains 2 separate arrays of Flash/EE memory, namely:

- 8 KBytes Internal Code Space and 640 Bytes Flash/EE Data Memory.

The 8 KBytes code space can be programmed in serial download

or parallel programming modes, while the 640 Byte data

space can be written by user software via a specified SFR interface.

Issue: In the temperature range -40°C to 0°C, this revision of silicon will not

support programming below DV_{DD}=3V supplies.

Work-Around: In the temperature range 0°C to 85°C, the device can be programmed at

 $DV_{DD} = 3.0V \pm 10\%$.

The device can be programmed at DV_{DD}=3.3V±10% over the full

temperature range -40°C to 85°C.

Related Issues: The device can be programmed at $DV_{DD}=5V\pm10\%$ over the full

temperature range -40°C to 85°C.

ADuC812 Errata Sheet

812 S06. FUNCTIONALITY OF PSMCON.1 BIT IN THE PSMCON SFR:

Background: The PSMCON.1 bit in the PSMCON SFR can be used to indicate which

supply caused the active power supply trip condition. PSMCON.1=0 indicates a DV_{DD} fault while PSMCON.1=1 indicates an AV_{DD} fault.

Issue: If the power supply trip point selection bits are set to select the 4.63V or

4.37V supply trip points, the PSMCON.1 (AV_{DD}/DV_{DD} power supply trip indicator) bit may not correctly indicate which supply has caused the fault. The supply trip indicator bit will function correctly at all other trip point

voltage levels.

Work-Around: Pending.

Related Issues: It should be noted that while the trip indicator bit function is suspect at

these trip levels, the PSM function itself is still 100% operational (even at 4.63V and 4.37V trip levels) generating an interrupt as soon as any one of the supply pins falls below the specified supply voltage trip point selection.

812_S07. EXTERNAL POWER-ON RESET (POR) OPERATION - DOCUMENTATION UPDATE:

All ADuC812 documentation has been updated to include a detailed recommendation on how the external RESET pin (#15) should be driven with external POR circuitry during power-on, power-down and brown-out conditions. These recommendations can be found in the ADuC812 technical datasheet (REVA) and the ADuC812 User's Manual (Draft 0.5) available at http://www.analog.com/microconverter

812_S08 RESET FUNCTIONALITY WHEN EXECUTING FROM EXTERNAL MEMORY ONLY:

Background: The ADuC812 can be reset using in three ways, namely a. Power cycling

the part, b. Toggling the reset pin and c. A watchdog Timeout

Issue: a. When executing from external memory only i.e. \overline{EA} tied low, resetting

the ADuC812 by toggling the RESET pin can cause the part to enter an

internal emulation mode.

b. When executing from external memory only i.e. \overline{EA} tied low, a

watchdog reset can cause the part to enter an internal emulation mode.

Work-Around: a. A subsequent toggle of the reset pin will reset the part.

b. Tying the PSEN pin low through an external pull-down resistor

(maximum value = 4KOhm) prevents entry to the emulation mode and

correctly resets the ADuC812.

Related Issues: a. This issue does not occur when executing code from <u>internal</u> memory

only.

b. This issue does not occur when executing code from both internal and

external code memory.

c. This issue does not occur when power cycling the ADuC812.