



- Magnetoresisitve sensor technology
- Linear signal output
- Over increased field range
- Very low hysteresis
- High sensititvity
- Substitutes KMZ10C / NXP

#### **DESCRIPTION**

Due to its featured properties - high sensitivity and almost no hysteresis – the **KMZ10CM** sensor is used in a wide range of applications, like magnetic field measurement, revolution counters, proximity detecting, and position measurement.

#### FEATURES APPLICATIONS

- Wheatsone bridge
- Passive output signal
- Linear signal output proportional to magnetic field strength
- 4 lead package for measurement of z direction

Detection of small magnetic fields, as in:

- · Contactless switch
- · Contactless displacement measurement
- · Current measurement

Polarity detection of small magnetic fields



#### PERFORMANCE SPECS

Parameter	Symbol	Condition	Min	Тур	Max	Unit
A. Operating Limits 1)						
max. supply voltage	$V_{CC,max}$				10	V
operating temperature	T <sub>op</sub>		-40		+150	°C
storage temperature	T <sub>st</sub>		-65		+165	°C
B. Sensor Specifications (T = 25 °C; H <sub>X</sub> = 3 kA/m)						
supply voltage	V <sub>CC</sub>			5	10	V
bridge resistance	$R_b$		1000	1400	1800	Ω
offset voltage	V <sub>OFF</sub> /V <sub>CC</sub>	H <sub>x</sub> =0	-1.5	0	+1.5	mV/V
sensitivity	S	note 2	1	1.2	2	(mV/V)/(kA/m)
hysteresis	$V_{HYST}$	note 3	-	-	100	μV/V
linearity deviation	FL	note 4	-	-	6.5	%
C. Sensor Specifications ( $T_{low} = 30  ^{\circ}\text{C}$ ; $T_{high} = 80  ^{\circ}\text{C}$ ; $H_X = 3  \text{kA/m}$ ; $V_{CC} = 5  \text{V}$ )						
TC of sensitivity	TCS	note 5	-	- 0.35	-	%/K
TC of resistance	TCBR	note 6	-	+ 0.45	-	%/K
TC of offset	TCV <sub>off</sub>	note 7,8, H <sub>x</sub> =0	-4	0	+4	μV/V/K

- Stress above one or more of the limiting values may cause permanent damage to the device. Exposure to limiting values for extended periods may affect device reliability.
- 2) The sensitivity is defined as the average slope of characteristic between Hy=0 and 6 kA/m and Hx=3kA/m:

$$S = \frac{V_0(H_y = 6kA/m) - V_0(H_y = 0)}{6*V_{CC}}$$

3) Hysteresis is defined as the difference between offset voltages measured without Hy-field after premagnetization by negative and positive Hy=±6 kA/m field:

$$V_{HYST} = V_0(H_1 \to H_0) - V_0(-H_1 \to H_0); H_0 = 0; H_1 = 6\frac{kA}{m}; H_X = 3\frac{kA}{m}; V_{CC} = 5V$$

4) The linearity error is the deviation of output voltage measured at Hy=3 kA/m from the average of Hy=0 and 6 kA/m-output voltages, expressed as percentage of the output voltage difference measured between 0 and 6 kA/m:

$$FL = \left| \frac{1}{2} - \frac{V_0(H_y = 3kA/m) - V_0(H_y = 0)}{V_0(H_y = 6kA/m) - V_0(H_y = 0)} \right| *100\%$$

5) The temperature coefficient of sensitivity is defined as the percentage change of the sensitivity per K referred to the value at T<sub>1</sub> = -25 °C; T<sub>2</sub>= operating temperature:

$$TCS = \frac{1}{(T_2 - T_1)} * \frac{S(T_2) - S(T_1)}{S(T_1)} * 100\%$$



The temperature coefficient of resistance is defined as the percentage change of the resistance per K referred to the value at  $T_1 = -25$  °C;  $T_2 = 0$ 0 operating temperature:


$$TCBR = \frac{1}{(T_2 - T_1)} * \frac{R(T_2) - R(T_1)}{R(T_1)} * 100\%$$

7) Temperature coefficient of offset voltage is defined as the voltage change per K expressed in  $\mu V/V$ :

$$TCV_{off} = \frac{V_{off}(T_2) - V_{off}(T_1)}{(T_2 - T_1)}$$


8) Linear behaviour assumed

#### **TYPICAL PERFORMANCE CURVES**



#### **FUNCTION**


#### **TERMINAL CONNECTIONS**



Pin	Symbol	Function
1	+Vo	positive output voltage
2	GND	negative supply voltage
3	-Vo	negative output voltage
4	+Vcc	positive supply voltage



#### **BLOCK DIAGRAM**



### **ORDERING CODE**

Product	Description	Part number
KMZ10CM	KMZ10 CM Linear Field Sensor	G-MRCO-028



#### **TECHNICAL CONTACT INFORMATION**

NORTH AMERICA	EUROPE	ASIA	
Measurement Specialties, Inc. 1000 Lucas Way Hampton, VA 23666 United States Phone: +1-800-745-8008 Fax: +1-757-766-4297 Email: sales@meas-spec.com Web: www.meas-spec.com	MEAS Deutschland GmbH Hauert 13 D-44227 Dortmund Germany Phone: +49-(0)231-9740-0 Fax: +49-(0)231-9740-20 Email: info.de@meas-spec.com Web: www.meas-spec.com	Measurement Specialties China Ltd. No. 26, Langshan Road High-tech Park (North) Nanshan District, Shenzhen 518057 China Phone: +86-755-33305088 Fax: +86-755-33305099 Email: info.cn@meas-spec.com Web: www.meas-spec.com	

The information in this sheet has been carefully reviewed and is believed to be accurate; however, no responsibility is assumed for inaccuracies. Furthermore, this information does not convey to the purchaser of such devices any license under the patent rights to the manufacturer. Measurement Specialties, Inc. reserves the right to make changes without further notice to any product herein. Measurement Specialties, Inc. makes no warranty, representation or guarantee regarding the suitability of its product for any particular purpose, nor does Measurement Specialties, Inc. assume any liability arising out of the application or use of any product or circuit and specifically disclaims any and all liability, including without limitation consequential or incidental damages. Typical parameters can and do vary in different applications. All operating parameters must be validated for each customer application by customer's technical experts. Measurement Specialties, Inc. does not convey any license under its patent rights nor the rights of others.

The status of this datasheet is PRELIMINARY

# **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

TE Connectivity: